DANLAW		FIR	
Product Code	DL545	Centralised ID	DTIL25030021
Customer	O.E	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	19-03-2025

SL No.	Description	Details	
1	Service Request Number	DTIL25030021	
2	Date of communication failure	N/A	
3	Device Model	DL545	
4	Defective device PSN	2307246150	
5	VIN Number	MB1TSKHD3PRFM5881	
6	Device IMEI	564324567890876	
7	Device CCID	8.991643013472648e+19	
8	Date of Sale of Device	N/A	
9	S Trigger Date	N/A	
10	C Trigger Date	N/A	
11	Commercial Expiry date	N/A	
12	Active Profile (BSNL/Airtel/Dual)	Airtel	
13	Vehicle Type / Model	Tipper	
14	Failure Location Plant/ Field- Customer Address UTTARPRADESH		
15	Kilometers/Hours	Hours	
16	Main Battery Voltage	24.0	
17	Service Engineer Name	Swamy	
18	Reason for Replacement/Repair		
19	Darby Last communication date	N/A	
20	Device Replacement request Initiation date	2025-03-19 18:12:55	
21	Returnable / Non-Returnable		

Approved By:	Name	Date	Signature
Initiated by- Service Eng.	Swamy	19-03-2025	Swamy
Service Manager		2025-03-19 18	13:18
Sales & Service Head	Rajendran Subramanian	2025-03-19 18	Rbs P