

Management Brief - Maintenance and Energy Performance

WORKFLOW AI DEMONSTRATION DATA • DUMMY DOCUMENT

1. Executive Overview

August 2026 performance remained stable, but several maintenance trends require proactive attention. The most significant mechanical concern is elevated vibration on Cooling Water Pump P-204.

2. Priority Issue

P-204 recorded 7.2 mm/s RMS vibration. The maintenance report recommends coupling inspection and laser alignment by 15 September 2026. The maintenance SOP classifies values above 7.1 mm/s RMS with a rapid increase as a critical condition requiring immediate escalation.

3. Cross-Functional Actions

Maintenance: inspect P-204 and verify alignment.

Data team: develop an integrated energy and maintenance dashboard.

Electrical team: provide renewable generation data.

Project management: consolidate recommendations for management.

4. Recommendation

Prioritize P-204 inspection while continuing development of the integrated monitoring dashboard. Use documented measurements and source references for management decisions.