
IP-52 Error code 125 (pg 1 of 1)

EC-125: Motor CTRL failed UX



2 Troubleshooting IP-52: Error code 125 2 - 145 LCx® Analyzer Service Manual (Text P/N 47278-102)

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	