

Line 3 Housing Defect Report

1. Identifiers

Site: Injection Molding Line 3

Incident Date: 2026-08-09

Severity: Cosmetic

2. Description

Line 3 produced housings with a hairline crack over a two hour window. See Figure 2 for the crack micrograph.

[FIGURE: pressure_compensation_curve.png]

3. Timeline

Cavity pressure deviation alarm at 06:31; first flagged part 06:40; production paused after hold at 11:40.

[FIGURE: trace.png]

4. Contributing Factors

Mold-controller firmware 2.1.1 was running on the affected line. Melt temperature drifted high.

5. Corrective Actions

Owner	Due Date	Action
-------	----------	--------

6. Approvals

Reviewer:

Signoff Date: