

TGX-9 North Ridge Incident Report

1. Identifiers

Site: North Ridge Relay Station

Incident Date: 2026-03-02

Severity: Low

2. Description

The TGX-9 gateway at North Ridge dropped 34 percent of inbound sensor packets over a two hour window. See Figure 2 for the network topology.

[FIGURE: cabinet_thermal_layout.png]

3. Timeline

Buffer occupancy alarm at 02:11; packet loss 02:14; recovery after manual power cycle at 06:31.

[FIGURE: figure1.png]

4. Contributing Factors

Firmware 4.2.0 was running on the affected unit. Cabinet temperature was elevated during the event.

5. Corrective Actions

Owner	Action	Due Date
-------	--------	----------

6. Approvals

Reviewer:

Signoff Date: