

Tail 512 Hydraulic Discrepancy Report

1. Identifiers

Site: Tail 512 Hydraulic System B

Incident Date: 2026-09-06

Severity: Routine

2. Description

Hydraulic System B on tail 512 showed slow pressure decay grounding the aircraft over a three hour window. See Figure 2 for the schematic.

[FIGURE: seal_wear_comparison.png]

3. Timeline

Hydraulic low advisory at 05:41; discrepancy logged 05:50; returned to service after seal replacement at 12:50.

[FIGURE: plot.png]

4. Contributing Factors

Actuator-controller software B2.5 was running on the affected unit. The actuator seal was degraded.

5. Corrective Actions

Action	Owner
--------	-------

6. Approvals

Reviewer:

Signoff Date: