# EX.NO.1.1-DESIGN AND DRAFT THE GIVEN 2D SKETCHES IN MODELLING SOFTWARE.

## AIM:


To create 2D mechanical component profile using Autodesk fusion software by applying the given dimensions ,radii,and diameters.

## Requirements:


Computer or laptop
Autodesk fusion software
Windows 10

## Procedure:


- Open autodesk fusion and select new and design.
- Select sketch and draw the circle at the centre with Ø 40mm and outer circle Ø66mm
- Draw the straight line at centre to upward 65mm and make a circle with Ø 20mm and outer circle Ø32mm.
- Connect the both circle with Ø66mm.And the bottom Ø50 downward and make a circle Ø10mm and outer circle Ø20.
- Join the circle with R20.
- And the side create line 47mm and down 26mm and make a circle R7 and outer circle R10.
- Join the circle at bottom R10 and up R20.
- And mirror the half part.




- After mirroring trim the remaining part of the cirle.
- At the centre circle draw the circle R6 and make 6 circle using circle patterns.
- And the dimensions like.
- Then extrude the design in the autodesk fusion.
- Then place the extrude part in drawing sheet in 2D. For dimensions




- Extrude in 15mm.




SKETCHES:

Then select the Finish sketch.And extrude the part .



OUTPUT:




RESULT:

Thus,the given sketch is drawn and drafted using a fusion 360 tool.