1.2:**Design and Draft the given 2D Sketches in modelling software.**

AIM:


To create 2D mechanical component profile using Autodesk fusion software by applying the given dimensions ,radii,and diameters.


Requirements:

Computer and laptop
Autodesk fusion
Windows10


Procedure :

- Open autodesk fusion and select new design and sketch.
- Draw four circle ,the inner circle R16 and next circle R21 and R32 and R40.
- The centre two circle and make a 6 circle with circle patterns.
- And top right circle top 60mm and side 50 mm make a circle R15 and R21.
- And side move 70mm and draw the circle R15 and R20.
- Mirror the top part to to down.
- Mirror the right side parts to left side by select the centre line.
- Trim the unwanted lines.
- For the dimensions for this.


- 

- And extrude the part in 15 mm.
- 

SKETCHES:



OUTPUT:



RESULT:

Thus, the given sketch is drawn and drafted using a fusion 360 tool.