VENUKATHIRAZHAGAN U

113323106116

II ECE

aut113323ec58

Phase 3: Implementation of Project

Title: Quality Control in Manufacturing

Objective

The objective of Phase 3 is to implement the core components of a manual and system-driven Quality Control (QC) process in a manufacturing environment. This phase includes establishing quality standards, inspection procedures, documentation protocols, and compliance mechanisms to ensure product consistency and reliability.

1. Establishing Quality Standards

Overview:
Defining clear, measurable quality standards is a fundamental part of manufacturing control. This phase focuses on setting acceptable tolerances and specifications for manufactured products.

Implementation:
• Specification Sheets: Product dimensions, materials, and performance criteria are documented.
• Industry Standards: QC benchmarks are aligned with relevant ISO standards or internal quality protocols.

Outcome:
At the end of this phase, every product category will have defined quality metrics and tolerances documented and approved.

2. Manual Inspection Procedures

Overview:
Visual and dimensional inspection procedures are introduced to identify defects or inconsistencies in products.

Implementation:
• Visual Checks: Trained inspectors visually assess products for surface defects, color mismatch, and label accuracy.
• Measurement Tools: Devices such as calipers, gauges, and micrometers are used to verify product dimensions.

Outcome:
By the end of this phase, inspection checkpoints are in place at various stages of the production line, ensuring early defect detection.

3. In-Process Quality Control (IPQC)

Overview:
IPQC focuses on monitoring and controlling the production process to maintain consistent quality before final output.

Implementation:
• Sampling Techniques: Periodic samples are pulled from the production line for inspection.
• Process Logs: Operators document key process parameters like temperature, pressure, and cycle time.

Outcome:
The process will be continuously monitored and adjusted to reduce variation and defect rates.

4. Final Product Testing

Overview:
Before delivery or packaging, a final inspection ensures that only quality-compliant products reach customers.

Implementation:
• Functional Testing: Products are tested for performance, load-bearing capacity, or other operational standards.
• Checklist Verification: A final quality checklist is used to confirm compliance with all required criteria.

Outcome:
Only products that pass all checks are labeled, packaged, and approved for shipment.

5. Documentation and Compliance

Overview:
Maintaining accurate records of all inspections and test results is critical for traceability and audits.

Implementation:
• Inspection Reports: Manual logs and checklists are filled out during each inspection step.
• Non-Conformance Reports: Defective items are documented and tracked for root cause analysis.

Outcome:
By the end of this phase, every inspection will be documented and stored for review, ensuring audit readiness and compliance with regulations.

6. Feedback and Corrective Action

Overview:
Quality control includes taking corrective actions based on recurring issues or customer feedback.

Implementation:
• Root Cause Analysis: Investigate trends in defects to determine the source of recurring problems.
• Corrective Actions: Processes or tooling are adjusted to prevent future defects.

Outcome:
Feedback loops ensure that quality issues are addressed quickly and improvements are integrated into the production cycle.

Challenges and Solutions

1. Inspector Variability:
   • Challenge: Different inspectors may interpret defects differently.
   • Solution: Standardized inspection criteria and regular training reduce subjectivity.

2. Manual Errors:
   • Challenge: Human errors in recording or inspection can occur.
   • Solution: Double-check systems and supervisor sign-offs help prevent documentation errors.

3. Time Constraints:
   • Challenge: Full inspections may slow down the production line.
   • Solution: Risk-based sampling ensures efficiency without sacrificing quality.

Outcomes of Phase 3

1. Defined Quality Standards: All products have clear and approved quality specifications.
2. Inspection Points: Visual, dimensional, and functional checks are implemented throughout production.
3. Documentation: All inspection and testing data is properly recorded and stored.
4. Final Testing: Every finished product is tested and verified before shipment.
5. Feedback Loop: Quality issues are tracked, analyzed, and used for continuous improvement.

Next Steps for Phase 4

Training and Certification: Further training for inspectors to improve consistency.
2. Digitalization: Begin transitioning paper checklists to digital systems (e.g., tablets, barcode scans).
3. Supplier Quality Assurance: Extend QC to raw material inspections and vendor quality assessments.

SOURCE CODE:

```python
# quality_control.py
1    # quality_control.py
2
3    def check_product(width, height, weight):
4        if 9.5 <= width <= 10.5 and 19.5 <= height <= 20.5 and 95 <= weight <= 105:
5            return "PASS"
6        else:
7            return "FAIL"
8
9    products = [
10       {"id": 1, "width": 10.0, "height": 20.0, "weight": 100},
11       {"id": 2, "width": 9.2, "height": 20.1, "weight": 96},
12       {"id": 3, "width": 10.3, "height": 21.0, "weight": 99}
13   ]
14
15   for p in products:
16       result = check_product(p["width"], p["height"], p["weight"])
17       print(f"Product {p['id']} - {result}")
18
```

OUTPUT:

```
PS C:\Users\spras\venu> & C:/Users/spras/AppData/Local/Microsoft/WindowsApps/python3.13.exe "c:/Users/spras/venu/# quality_control.py"
Product 1 - PASS
Product 2 - FAIL
Product 3 - FAIL
PS C:\Users\spras\venu>
```