

## 5050 E SMITH RD

DENVER CO 80216

PROPERTY TYPE  
INDUSTRIAL-AUTO SERVICE GARAGE 332:...

YEAR BUILT  
2019

BUILDING AREA  
29,295 SF

ROOF SQUARES  
293

PARCEL ID  
0119400250000



### OVERALL ROOF CONDITION SCORE

**66** /100  
FAIR

### RISK LEVEL

MODERATE



### ROOF INFORMATION

|                  |                                                                                                                                                                                                                                    |
|------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| ROOF TYPE        | Low-slope commercial roof                                                                                                                                                                                                          |
| ROOF SYSTEM      | Primary: PVC or Coated Roof; Secondary: TPO/PVC                                                                                                                                                                                    |
| VISIBLE CONCERNS | dark staining/color variation; many penetrations/units; Several darkened rooftop areas/discoloration spots are visible on the white roof field, suggesting possible localized staining, repairs, or moisture/ponding-related wear. |
| ROOF AGE EST.    | Likely relatively new or recently renewed at time of imagery; apparent roof field looks clean and bright, though aerial imagery alone cannot confirm installation date or membrane type.                                           |
| ROOF AREA        | 29,295 SF                                                                                                                                                                                                                          |
| ROOF PITCH       | Low-slope / near-flat                                                                                                                                                                                                              |
| CONFIDENCE       | 76%                                                                                                                                                                                                                                |

SELECTED AERIAL IMAGE - DENVER GIS AS OF 03/11/2018 - 03/17/2018

### ROOF CONDITION BREAKDOWN

|                     |                        |        |
|---------------------|------------------------|--------|
| Membrane Condition  | <div><div></div></div> | 64/100 |
| Ponding             | <div><div></div></div> | 70/100 |
| Flashing & Seals    | <div><div></div></div> | 60/100 |
| Penetrations        | <div><div></div></div> | 58/100 |
| Overall Maintenance | <div><div></div></div> | 62/100 |

### AERIAL ROOF OBSERVATIONS

1. White low-slope commercial roof with generally uniform reflective appearance.
2. Visible seams or joints run through the roof field, supporting a membrane or coated-membrane system.
3. Scattered dark spots and irregular discoloration are present on the roof surface.
4. Numerous rooftop units/penetrations and related curbs are visible, creating additional leak-prone details.
5. No clear standing water is visible in this aerial frame.

### BUILDING CHARACTERISTICS

|                   |                     |
|-------------------|---------------------|
| LAND AREA         | 2.13 acres          |
| STORIES           | -                   |
| CONSTRUCTION TYPE | 332: SERVICE GARAGE |
| TAX DISTRICT      | DENV                |
| LAND VALUE        | \$1,389,900         |

### REPORT SUMMARY

Aerial imagery from 03/11/2018 - 03/17/2018 shows a low-slope commercial roof that appears generally serviceable and relatively recent-looking, with a bright white reflective surface consistent with a membrane or coated-membrane system. Visible darkened spots and localized discoloration introduce some concern for staining, prior repairs, or moisture-related wear, and the roof also has multiple penetrations/equipment that increase flashing and seal risk. No obvious ponded

#### Recommendation:

The roof appears to be in good-fair condition overall, but the visible staining/discoloration and multiple penetrations warrant an onsite commercial roof inspection focused on flashing, seams, and any localized moisture-related distress. If the roof is otherwise sound and restoration-eligible, have a qualified commercial roof-coating contractor evaluate whether a silicone roof restoration is appropriate before considering a more costly overlay or replacement; a qualifying silicone system may reduce tear-off waste, cost, and disruption, create a seamless reflective cool-roof surface, help with ponding water resistance when properly designed and installed, improve UV and hail resistance, and may qualify for a manufacturer warranty of up to 20 years. If field testing or onsite inspection finds widespread moisture, failed insulation, structural/deck deterioration, or an incompatible substrate, pursue overlay or replacement evaluation. A one

### ROOF REPAIR OPTIONS

#### Roof Replacement Cost Estimate

|                    |                                       |
|--------------------|---------------------------------------|
| TOTAL PROJECT COST | COST SUMMARY                          |
| <b>\$791,697</b>   | Replacement Subtotal <b>\$688,432</b> |
| \$23.50 / SF       | Contingency (15%) <b>\$103,265</b>    |
|                    | Total Project Cost <b>\$791,697</b>   |

#### Roof Overlay Cost Estimate

|                    |                                     |
|--------------------|-------------------------------------|
| TOTAL PROJECT COST | COST SUMMARY                        |
| <b>\$306,133</b>   | Overlay Subtotal <b>\$278,302</b>   |
| \$9.50 / SF        | Contingency (10%) <b>\$27,830</b>   |
|                    | Total Project Cost <b>\$306,133</b> |

#### Roof Coating Estimate

|                              |                         |                              |
|------------------------------|-------------------------|------------------------------|
| TOTAL PROJECT COST           | WARRANTY TERM           | BUDGETARY COST RANGE         |
| <b>\$102,532 - \$175,770</b> | <b>10 Year Warranty</b> | <b>\$102,532 - \$117,180</b> |
| \$3.50 - \$6.00 / SF         | <b>15 Year Warranty</b> | <b>\$131,828 - \$146,475</b> |
|                              | <b>20 Year Warranty</b> | <b>\$161,122 - \$175,770</b> |

Cost estimates are derived from publicly available information and proprietary commercial roofing analysis models and are intended for preliminary budgeting and planning purposes only. Roof-area measurements do not include the vertical surface area of parapet walls. They should not be considered a contractor quote, engineering assessment, or guarantee of actual project costs. Estimates do not include additional repairs or unforeseen conditions that may be identified during an on-site inspection.