

4100 N DAHLIA ST

DENVER CO 80216

PROPERTY TYPE
INDUSTRIAL-WAREHOUSE 398: WAREHOU...

YEAR BUILT
1971

BUILDING AREA
31,025 SF

ROOF SQUARES
310

PARCEL ID
0119400266000



OVERALL ROOF CONDITION SCORE

64 /100
FAIR

RISK LEVEL

MODERATE



ROOF INFORMATION

ROOF TYPE	Low-slope commercial warehouse roof
ROOF SYSTEM	Primary: Primary roof field appears to be a low-slope membrane roof, with likely white single-ply or coated membrane on the south/east building and dark low-slope membrane on the north/east building; exact chemistry is not fully resolvable from aerial imagery alone.; Secondary: TPO/PVC, EPDM
VISIBLE CONCERNS	dark staining/color variation; many penetrations/units; Dark uniform roof areas and isolated discoloration are visible on the darker roof field; these may reflect membrane aging, staining, or prior repairs.
ROOF AGE EST.	Likely original-era or older low-slope commercial roofing consistent with a 1971 industrial building, though apparent surface condition suggests at least some areas may have been resurfaced or replaced since original construction.
ROOF AREA	31,025 SF

SELECTED AERIAL IMAGE - DENVER GIS AS OF 03/11/2018 - 03/17/2018

ROOF CONDITION BREAKDOWN

Membrane Condition		62/100
Ponding		67/100
Flashing & Seals		60/100
Penetrations		58/100
Overall Maintenance		62/100

AERIAL ROOF OBSERVATIONS

1. Industrial warehouse property with multiple flat/low-slope roof sections.
2. One roof field appears dark and uniform; another appears bright white, indicating different roof surfaces or a reflective surface treatment.
3. Multiple rooftop penetrations are visible, including small vents/curbs and mechanical-related protrusions.
4. Perimeter drainage and edge conditions are visible but not clearly showing severe blockage from the aerial view.
5. No obvious tree overhang onto the roof is visible in this image.

BUILDING CHARACTERISTICS

LAND AREA	1.02 acres
STORIES	-
CONSTRUCTION TYPE	398: WAREHOUSE
TAX DISTRICT	DENV
LAND VALUE	\$669,100

REPORT SUMMARY

Aerial imagery dated 03/11/2018 - 03/17/2018 shows a low-slope industrial warehouse roof with mixed roof field appearances: one dark membrane field and one bright white reflective field. Visible condition appears generally serviceable, but the darkened roof area and isolated discoloration suggest aging, prior repair activity, or localized moisture-related staining potential. Multiple penetrations and rooftop details increase flashing and seal risk. No clear severe ponded

Recommendation:

Have a qualified commercial roofing contractor perform an onsite inspection, including moisture testing where warranted, to confirm the roof system, identify any required repairs, and verify whether a silicone roof restoration is appropriate for the apparently restorable low-slope areas before considering overlay or replacement. A properly designed and installed silicone system can reduce tear-off waste, cost, and disruption, create a seamless monolithic white reflective cool-roof surface, withstand ponding water when properly designed and installed, improve UV and hail resistance, and may qualify for a manufacturer warranty of up to 20 years. If onsite findings show widespread moisture, failed insulation, structural or deck deterioration, or incompatible substrate conditions, pursue overlay or full replacement evaluation instead.

ROOF REPAIR OPTIONS

Roof Replacement Cost Estimate

TOTAL PROJECT COST	COST SUMMARY
\$874,129	Replacement Subtotal \$760,112
\$24.50 / SF	Contingency (15%) \$114,017
	Total Project Cost \$874,129

Roof Overlay Cost Estimate

TOTAL PROJECT COST	COST SUMMARY
\$332,743	Overlay Subtotal \$302,494
\$9.75 / SF	Contingency (10%) \$30,249
	Total Project Cost \$332,743

Roof Coating Estimate

TOTAL PROJECT COST	WARRANTY TERM	BUDGETARY COST RANGE
\$108,588 - \$186,150	10 Year Warranty	\$108,588 - \$124,100
\$3.50 - \$6.00 / SF	15 Year Warranty	\$139,612 - \$155,125
	20 Year Warranty	\$170,638 - \$186,150

Cost estimates are derived from publicly available information and proprietary commercial roofing analysis models and are intended for preliminary budgeting and planning purposes only. Roof-area measurements do not include the vertical surface area of parapet walls. They should not be considered a contractor quote, engineering assessment, or guarantee of actual project costs. Estimates do not include additional repairs or unforeseen conditions that may be identified during an on-site inspection.