Wiring Diagram v001 (WIP)

Dustie Mk2

aka 'The VHS Wood CNC'

240v R, S, PE
AC EMI Filter
L
N
GND
PSU · 350 W · 48 V
Y1 Stepper, Y2 Stepper
V+ V+ V+ V- V- V- PE N L
PSU · 350 W · 48 V
X Stepper, Z Stepper
PSU · 350 W · 24 V
Mesa 7i76EU, Rotary Axis A, Field Power
PSU · 120 W · 24 V
Mesa 7i76EU
Lenovo PC · LinuxCNC
← DVI to HDMI →
USB Extension
Inside Cabinet
Outside Cabinet
Ethernet
R
S
T
P+
PR
U
V
W
GND
U
V
W
GND
HY-DIV268N-5A
FRAME GROUND
RJ45 ETH
Mesa 7i76EU
Breakout Box 1
Static Platform
aka 'The Table'
Breakout Box 2
X Platform
aka 'The Gantry'
Breakout Box 3
Z Platform
aka 'The Toolhead'
Y1 Drag Chain
X Drag Chain
Power and Signal bundles separated in drag chain
DSUB, multiple as required
×23 signal wires
×18 signal wires
×7 signal wires
Stepper Y1
Stepper Y2
Stepper X
Stepper Z
PNP
NO & NC
SHARK Touch Plate
Static Platform Sensors
Endstops: Y+, Y-
Home Sensors: Y1, Y2
Touch Plate
Y Platform Sensors
Endstops: X+, X-
Home Sensors: X
Z Platform Sensors
Endstops: Z+, Z-
Home Sensors: Z