


Appearance and Drawings



Colour and material are not the same thing

COLOUR

- Select the part, open the **View** tab, set **Shape Appearance**.
- For a whole assembly, set it on the **link** and tick override.
- Group by function: frame red, tynes dark, wear parts bright.


MATERIAL

- Select the body and open the **Material** panel.
- Choose **Steel**.
- This sets the density, so the weight FreeCAD reports means something.


Every weight quoted in this course came out of the model this way. That is the difference between modelling and drawing.

HIDE THE SKETCHES FIRST


Getting a clean picture



Making a drawing



What each sheet should show



Which format to send

FORMAT	CARRIES	SEND IT FOR
STEP	exact solids and colours	anything going to another CAD system
DXF	flat outlines	laser and plasma cutting
STL	a triangle mesh	3D printing only
FCStd	everything, editable	a colleague who has to change it

STEP throws away the history. The person receiving it gets the solid, not your sketches or your spreadsheet. That is usually what you want for a supplier, and a disaster for a colleague.

CUTTING THE BLADE BLANK

- Because we swept the blade along an arc of known length, the flat blank is exactly 13 by 4 inches.
- No bend allowance to work out.
- Export the plan outline to DXF from a TechDraw top view.