

PM Testing flow

pm -3

Location:	Status:	Score:
SSM455	failed	25.0%

Initiated By : Kumaran GU

Prefix : pm -3

Submission Date : 05-Jul-2026 11:53 PM

Designation, Dept : Manager, Quality

Audit Summary

Audit Summary	Score (%)	Score Critical Fail	Task Completion (%)	Overdue (%)	Reopened (%)
Status: failed	25.0%	0	1	0	0
Group 1	25%	0	1	0	0

Form Details:

Audit Info					
Item	Response	Image	Remarks	Consumed from / SAP Code or Product Name	After image
Audit Guidelines					
Audited Location	SSM455				

Group 1					
Item	Response	Image	Remarks	Consumed from / SAP Code or Product Name	After image
Rust on the bolts	OK		Ok		
Rust on the bolts (Copy)	Not OK (GTC)		Gtc	Activity	
Rust on the bolts (Copy 2)	Not OK (NGTC)		Ngtc	150045 - 30kV 10kA Station Class-II Polymeric Lightning Arrester (Orange Power 33kv la)	
Rust on the bolts (Copy 3)	OK		Jj		

PM Testing flow

pm -4

Location:	Status:	Score:
-	Completed	N/A

Initiated By :Kumaran GU

Prefix :pm -4

Submission Date :05-Jul-2026 11:54 PM

Designation, Dept :Manager, Quality

Form Details:

Audit Info					
Item	Response	Image	Remarks	Consumed from / SAP Code or Product Name	After image
Audit Guidelines					
Audited Location					

Group 1					
Item	Response	Image	Remarks	Consumed from / SAP Code or Product Name	After image
Rust on the bolts					
Rust on the bolts (Copy)					
Rust on the bolts (Copy 2)					

Group 1					
Item	Response	Image	Remarks	Consumed from / SAP Code or Product Name	After image
Rust on the bolts (Copy 3)					