

## Trainings ▾

### Inspect

Every 6000 hours or 2 years inspect the fan hub for wobble and grease leakage. Replace with a new or rebuilt unit as necessary.

Refer to a Cummins Authorized Repair Location for removal and replacement of fan hub.

