

Trainings ▾

Inspect

Note : A minor chemical build up or streaking at the water pump weep hole is normal. Do not repair or replace the water pump unless an actual leak is confirmed. Contact a Cummins® Authorized Repair Location.

Every 6000 hours or 2 years inspect the water pump for coolant or oil leakage at the water pump weep hole.

