

Trainings ▾

Inspect

Every 6000 hours or 2 years, inspect the fan hub for wobble and grease leakage. Replace with a new or rebuilt fan hub, as necessary. Contact a Cummins® Authorized Repair Location for replacement.

