



Service Bulletin Number: 6458441

Released Date: 01-mar-2023

Engine Control Module (ECM) Replacements Outside of Published Troubleshooting

Engine Control Module (ECM) Replacements Outside of Published Troubleshooting

Product Affected

- All engine models equipped with an engine control module (ECM)

Summary

ECMs have been found to have a higher than expected rate of analysis results being Trouble Not Found (TNF).

Issue

- Repeat malfunctions, fault codes, or symptoms resulting in an incorrect replacement of an ECM.

Root Cause

- ECMs are being replaced outside of published troubleshooting.
- Technical escalation process is **not** being followed.

Resolution

- The ECM claim may be subject to adjustment or denial if replaced outside of published troubleshooting or escalation process. See warranty memo M2202 and M2206 for more information.
- Watch the video below to understand options prior to an ECM replacement that is not supported by published troubleshooting or diagnostics.

Note : http://tsb.cumminsvirtualcollege.com/6458441_en.aspx
(http://tsb.cumminsvirtualcollege.com/6458441_en.aspx)

- If necessary, follow the technical escalation process prior to replacing the ECM

Document History

Date	Details
2023-3-1	Module Created
2023-12-11	Updated video link.

