

Manual Change History (4326169) QSB6.7 CM2150 B109 Fault Code Troubleshooting Manual

Date	26-Sep-2013
Section	Back
Procedure Number	4326169-history (/qs3/pubsys2/xml/en/manual/4326169/4326169-history.html)
Procedure Title	Manual Change History
Update Reason	New manual for QSB6.7 CM2150 B109 engine released for use.

Date	16-Dec-2013
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	178-t05-111 (/qs3/pubsys2/xml/en/procedures/178/178-t05-111.html)
Procedure Title	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Update Reason	Added two engine models to the Associated Procedures Table.

Date	16-Dec-2013
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	178-t05-122 (/qs3/pubsys2/xml/en/procedures/178/178-t05-122.html)
Procedure Title	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Update Reason	Added two engine models to the Associated Procedures Table.

Date	16-Dec-2013
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	178-t05-123 (/qs3/pubsys2/xml/en/procedures/178/178-t05-123.html)
Procedure Title	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Update Reason	Added two engine models to the Associated Procedures Table.

Date	16-Dec-2013
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	178-t05-131 (/qs3/pubsys2/xml/en/procedures/178/178-t05-131.html)
Procedure Title	Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Update Reason	Added two engine models to the Associated Procedures Table.

Date	16-Dec-2013
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	178-t05-132 (/qs3/pubsys2/xml/en/procedures/178/178-t05-132.html)
Procedure Title	Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Update Reason	Added two engine models to the Associated Procedures Table.

Date	16-Dec-2013
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	178-t05-133 (/qs3/pubsys2/xml/en/procedures/178/178-t05-133.html)
Procedure Title	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Update Reason	Added two engine models to the Associated Procedures Table.

Date	16-Dec-2013
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	178-t05-134 (/qs3/pubsys2/xml/en/procedures/178/178-t05-134.html)
Procedure Title	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Update Reason	Added two engine models to the Associated Procedures Table.

Date	16-Dec-2013
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	178-t05-135 (/qs3/pubsys2/xml/en/procedures/178/178-t05-135.html)
Procedure Title	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Update Reason	Added two engine models to the Associated Procedures Table.

Date	16-Dec-2013
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	178-t05-141 (/qs3/pubsys2/xml/en/procedures/178/178-t05-141.html)
Procedure Title	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Update Reason	Added two engine models to the Associated Procedures Table.

Date	22-Feb-2016
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	178-t05-234 (/qs3/pubsys2/xml/en/procedures/178/178-t05-234.html)
Procedure Title	Injector Solenoid Driver Cylinder 3 Circuit - Current Below Normal or Open Circuit
Update Reason	Changed Step 1D from: 3200 rpm to: high idle speed, from: or past 3400 rpm, followed by moderate deceleration to 3400 rpm, to: the engine tachometer red area.

Date	20-Apr-2017
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	178-t05-1117 (/qs3/pubsys2/xml/en/procedures/178/178-t05-1117.html)
Procedure Title	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Update Reason	Added Step 3C - Check battery ground(s), engine block, and chassis ground.

Date	28-Jun-2017
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	178-t05-272 (/qs3/pubsys2/xml/en/procedures/178/178-t05-272.html)
Procedure Title	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Above Normal or Shorted to High Source
Update Reason	Updated Step 3C to check open return circuit.

Date	04-Jan-2019
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	178-t05-286 (/qs3/pubsys2/xml/en/procedures/178/178-t05-286.html)
Procedure Title	SAE J1939 Multiplexing Configuration Error - Out of Calibration
Update Reason	Updated step 2A to give more clarification.
Date	03-Nov-2021
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	178-t05-351 (/qs3/pubsys2/xml/en/procedures/178/178-t05-351.html)
Procedure Title	Injector Power Supply - Bad Intelligent Device or Component
Update Reason	Removed instruction to disconnect the ECM power supply harness from the battery terminals in step 2C.

Last Modified: 05-Nov-2021
