

Manual Change History (4358378) Cummins® Electronic Throttle and Shift (ETS) and Cummins® Inboard Joystick Marine Controls MC101 Master Repair Manual

Date	06-May-2014
Section	Back
Procedure Number	4358378-history (/qs3/pubsys2/xml/en/manual/4358378/4358378-history.html)
Procedure Title	Manual Change History
Update Reason	New manual for engine released for use.

Date	05-Sep-2014
Section	Back
Procedure Number	4358378-history (/qs3/pubsys2/xml/en/manual/4358378/4358378-history.html)
Procedure Title	Manual Change History
Update Reason	Phoenix Phase 2.

Date	23-Dec-2014
Section	Section 9 - Drive Units - Group 09
Procedure Number	326-009-063-tr (/qs3/pubsys2/xml/en/procedures/326/326-009-063-tr.html)
Procedure Title	Drive Leg
Update Reason	Updated test block section for the isolation test method for metal hulls.

Date	23-Dec-2014
Section	Section 9 - Drive Units - Group 09
Procedure Number	326-009-064 (/qs3/pubsys2/xml/en/procedures/326/326-009-064.html)
Procedure Title	Mounting Flange
Update Reason	Updated test block section for the isolation test method for metal hulls.

Date	01-May-2017
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4358378-t214-tr (/qs3/pubsys2/xml/en/manual/4358378/4358378-t214-tr.html)
Procedure Title	Thruster(s) Will Not Respond To Inboard Joystick Operation
Update Reason	Troubleshooting trees were updated to include changes for a CIJ software change being released to marine customers.

Date	01-May-2017
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4358378-t219-tr (/qs3/pubsys2/xml/en/manual/4358378/4358378-t219-tr.html)
Procedure Title	Vessel Responds Slowly or Incorrectly During Thruster Operation
Update Reason	Troubleshooting trees were updated to include changes for a CIJ software change being released to marine customers.

Date	02-Aug-2019
Section	Section 15 - Instruments and Controls
Procedure Number	326-015-177 (/qs3/pubsys2/xml/en/procedures/326/326-015-177.html)
Procedure Title	Dual Relay Module
Update Reason	Added to manual.

Date	02-Aug-2019
Section	Section 15 - Instruments and Controls
Procedure Number	326-015-178 (/qs3/pubsys2/xml/en/procedures/326/326-015-178.html)
Procedure Title	Transparent Transfer
Update Reason	Added to manual.

Date	09- Sep-2019
Section	Section E - Product and System Identification
Procedure Number	326-208-002 (/qs3/pubsys2/xml/en/procedures/326/326-208-002.html)
Procedure Title	Component Identification
Update Reason	CIJ/ETS product improvements.
Date	13-Sep-2019
Section	Section 15 - Instruments and Controls
Procedure Number	326-015-054 (/qs3/pubsys2/xml/en/procedures/326/326-015-054.html)
Procedure Title	Component Diagrams
Update Reason	CIJ/ETS product improvements drive changes.
Date	21-Oct-2019
Section	Section E - Product and System Identification
Procedure Number	326-208-001 (/qs3/pubsys2/xml/en/procedures/326/326-208-001.html)
Procedure Title	Component Identification
Update Reason	CIJ/ETS product improvements.
Date	04-Nov-2019
Section	Section 15 - Instruments and Controls - Group 15
Procedure Number	326-015-044 (/qs3/pubsys2/xml/en/procedures/326/326-015-044.html)
Procedure Title	Managing Vessel Personalities
Update Reason	Added information about the QuickServe® Marine Panel Firmware webpage and included a hyperlink to the webpage.

Date	04-Nov-2019
Section	Section 15 - Instruments and Controls - Group 15
Procedure Number	326-015-074 (/qs3/pubsys2/xml/en/procedures/326/326-015-074.html)
Procedure Title	Component Software Download Tool
Update Reason	Added information and a hyperlink to the Marine Panel Firmware Updates - Cummins Inboard Joystick webpage in the Troubleshooting steps.
Date	04-Nov-2019
Section	Section 15 - Instruments and Controls - Group 15
Procedure Number	326-015-075 (/qs3/pubsys2/xml/en/procedures/326/326-015-075.html)
Procedure Title	Component Software Management
Update Reason	Added notes and information about the Marine Panel Firmware Updates - Cummins Inboard Joystick webpage.
Date	24-Jan-2020
Section	Section 15 - Instruments and Controls - Group 15
Procedure Number	326-015-042 (/qs3/pubsys2/xml/en/procedures/326/326-015-042.html)
Procedure Title	Vessel Configuration Tool
Update Reason	Added link to Marine Panel Firmware Updates - Cummins Inboard Joystick webpage.

Last Modified: 24-Jan-2020
