



Technical Service Bulletin

Technical Service Bulletin: tsb090018

Released Date: 04-Oct-2018

INSITE™ 7.2 and PowerMatch™ Calibrations Issue

INSITE™ 7.2 and PowerMatch™ Calibrations Issue

Core Issue

This Early Field Notification describes an issue with INSITE™ 7.2 and PowerMatch™ calibrations. When attempting to transfer the PowerMatch™ calibration, INSITE™ 7.2 will show an error window and then close.

Confirmation

QSB3.3 CM2150

QSB5.9 CM850

QSB4.5 CM850

QSB6.7 CM850

QSC8.3 CM554

QSC8.3 CM850

QSL9 CM554

QSL9 CM850

QSM11 CM570

QSX15 CM570

When trying to send a PowerMatch™ calibration with INSITE™ 7.2, an INSITE™ Service Diagnostic Program window will appear with Debug or Close options. An INSITE™ Service Diagnostic Program with Error Signature information and a Close button will appear. Clicking Close will close INSITE™ 7.2.

None

None

None

Resolution

Download INSITE™ 7.2 Service Pack 1 from INSITE™ website:

<http://care.cummins.com>

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2018-10-4	Corrected URL

Last Modified: 04-Oct-2018
