



Technical Service Bulletin

Technical Service Bulletin: tsb100678

Released Date: 07-Mar-2008

Fuel Metering and Timing Actuators

Fuel Metering and Timing Actuators

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin provides information on obsoleted ISX actuators, Part Numbers 4089982 and 4089984, with no supersession available.

When ordering actuators for ISX engines equipped with actuator Part Numbers 4002070, 4089541, or 4089984, there will be no superseding part numbers available. The same will be true for actuator Part Numbers 4002071, 4089539, and 4089982. Part Numbers 4089982, and 4089984 have been superseded in North America, but are still available for Scania™ applications. For this reason, superseding Part Numbers for 4089982 and 4089984 are **not** available on Quickservice™ Online. The correct replacement actuator for Part Number 4089982 is 4089428RX. The correct replacement actuator for Part Number 4089984 is 4089540RX. Please note that, for North American Cummins® engine applications the RX part numbers **must** be used.

Actuator Part Numbers			
Original	Superseded to	Superseded to	Superseded to
4002070	4089541	4089984 ¹	4089540RX ²
4002071	4089539	4089982 ¹	4089428RX ²
¹ Present part number for Scania™			
² Present part number for Cummins® North America			