



Technical Service Bulletin

Technical Service Bulletin: tsb101148	Released Date: 10-May-2002
Piston and Connecting Rod Assembly	

Piston and Connecting Rod Assembly

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic updates the assemble section of procedure 001-054 in the L10, M11, ISM, and QSM11, Troubleshooting and Repair Manuals.

Note : This is a product improvement and is not subject to campaign.

Last Modified: 10-May-2002
