



Technical Service Bulletin

Technical Service Bulletin: tsb101232	Released Date: 19-Dec-2002
Revision to Procedure 003-011, Rocker Lever Cover	

Revision to Procedure 003-011, Rocker Lever Cover

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic revises Procedure 003-011, Rocker Lever Cover, for Signature, ISX, and QSX15 Series Engines.

Last Modified: 19-Dec-2002
