



Technical Service Bulletin

Technical Service Bulletin: tsb101246	Released Date: 28-Jan-2003
Lubricating System Cleaning and Flushing	

Lubricating System Cleaning and Flushing

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic updates the cleaning section of the Rocker Lever Cover Procedure 003-011 for the Signature, ISX, and QSX15 Base Engine Troubleshooting and Repair Manual, Bulletin 3666239.

Last Modified: 28-Jan-2003
