



Technical Service Bulletin

Technical Service Bulletin: tsb101258	Released Date: 10-Apr-2003
Revision to Procedures 008-018 and 008-019	

Revision to Procedures 008-018 and 008-019

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic updates Procedure 008-018, Radiator Cap Pressure Release Test, and Procedure 008-019, Air or Combustion Gas in Cooling System, in the Signature, ISX, and QSX15 Base Engine Troubleshooting and Repair Manual, Bulletin 3666239.

Last Modified: 10-Apr-2003
