



Technical Service Bulletin

Technical Service Bulletin: tsb101262	Released Date: 10-Apr-2003
Revision to Procedure 002-016, Valve Guide Seal, Cylinder Head	

Revision to Procedure 002-016, Valve Guide Seal, Cylinder Head

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic updates Procedure 002-016, Valve Guide Seal, Cylinder Head in the Signature, ISX, and QSX15 Troubleshooting and Repair Manual, Bulletin 3666239.

Last Modified: 10-Apr-2003
