



Technical Service Bulletin

Technical Service Bulletin: tsb101264	Released Date: 10-Apr-2003
Revision to Procedure 002-004, Cylinder Head	

Revision to Procedure 002-004, Cylinder Head

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic updates Procedure 002-004, Cylinder Head, for the Signature, ISX, and QSX15 Base Engine Troubleshooting and Repair Manual, Bulletin 3666239.

Last Modified: 10-Apr-2003
