



Technical Service Bulletin

Technical Service Bulletin: tsb101265	Released Date: 17-Apr-2003
Revision to Procedure 008-047, Radiator Pressure Cap	

Revision to Procedure 008-047, Radiator Pressure Cap

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic revises Procedure 008-047 in the Signature, ISX, and QSX15 Base Engine Troubleshooting and Repair Manual, Bulletin 3666239.
--

Last Modified: 17-Apr-2003
