



Technical Service Bulletin

Technical Service Bulletin: tsb101295	Released Date: 23-Jul-2003
Fault Code 254 Troubleshooting Tree Update	

Fault Code 254 Troubleshooting Tree Update

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic updates Fault Code 254 - Fuel Shutoff Valve Solenoid Supply Circuit in the Troubleshooting and Repair Manual, Signature, ISX and QSX15 Engines, Bulletin 3666259 (</qs3/portal/manualviewer.html?path=/qs3/pubsys2/xml/en/outlines/3666259.html>).

Last Modified: 23-Jul-2003
