



Technical Service Bulletin

Technical Service Bulletin: tsb101297

Released Date: 30-Jul-2003

Update to Procedure 005-043 (Fuel Shutoff Valve)

Update to Procedure 005-043 (Fuel Shutoff Valve)

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic is to update procedure 005-043 (/qs3/pubsys2/xml/en/procedures/10/10-005-043.html) in Troubleshooting and Repair Manual, Signature, ISX and QSX15 Engines, Bulletin 3666239.

Related Procedures

10-005-043

(/qs3/pubsys2/xml/en/procedures/10/10-005-043.html)

Fuel Shutoff Valve

(/qs3/pubsys2/xml/en/procedures/10/10-005-043.html)

Last Modified: 30-Jul-2003