



Technical Service Bulletin

Technical Service Bulletin: tsb101298

Released Date: 08-Aug-2003

Update to Procedure 001-026, Cylinder Block

Update to Procedure 001-026, Cylinder Block

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic updates Procedure 001-026 (</qs3/pubsys2/xml/en/procedures/10/10-001-026.html>), Cylinder Block, in Troubleshooting and Repair Manual, Signature, ISX and QSX15 Engines, Bulletin 3666239.

A repair step has been added to repair minor defects in the cylinder block using a taper-threaded plug.

Related Procedures

10-001-026
(</qs3/pubsys2/xml/en/procedures/10/10-001-026.html>)

Cylinder Block
(</qs3/pubsys2/xml/en/procedures/10/10-001-026.html>)

Last Modified: 08-Aug-2003