



Technical Service Bulletin

Technical Service Bulletin: tsb101301

Released Date: 08-Sep-2003

Revision to Procedure 010-050, Turbocharger Wastegate Actuator

Revision to Procedure 010-050, Turbocharger Wastegate Actuator

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic revises Procedure 010-050 (/qs3/pubsys2/xml/en/procedures/10/10-010-050.html), Turbocharger Wastegate Actuator for the Signature, ISX, and QSX15 Base Engine Troubleshooting and Repair Manual, Bulletin 3666239.

Related Procedures

10-010-050
(/qs3/pubsys2/xml/en/procedures/10/10-010-050.html)

Turbocharger Wastegate Actuator
(/qs3/pubsys2/xml/en/procedures/10/10-010-050.html)

Last Modified: 08-Sep-2003