



Technical Service Bulletin

Technical Service Bulletin: tsb101334	Released Date: 03-Nov-2003
Revision to Procedure 001-054	

Revision to Procedure 001-054

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 001-054, Piston and Connecting Rod Assembly.

Related Procedures

10-001-054 (/qs3/pubsys2/xml/en/procedures/10/10-001-054.html)	Piston and Connecting Rod Assembly (/qs3/pubsys2/xml/en/procedures/10/10-001-054.html)
---	---

Last Modified: 03-Nov-2003
