



Technical Service Bulletin

Technical Service Bulletin: tsb101411

Released Date: 30-Mar-2004

Revisions to Procedures 001-043 and 001-054

Revisions to Procedures 001-043 and 001-054

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose of this Service Parts Topic is to revise Procedure 001-043 Piston and Procedure 001-054 Piston and Connecting Rod Assembly.

Related Procedures

10-001-043 (/qs3/pubsys2/xml/en/procedures/10/10-001-043.html)	Piston (/qs3/pubsys2/xml/en/procedures/10/10-001-043.html)
10-001-054 (/qs3/pubsys2/xml/en/procedures/10/10-001-054.html)	Piston and Connecting Rod Assembly (/qs3/pubsys2/xml/en/procedures/10/10-001-054.html)

Last Modified: 30-Mar-2004