



Technical Service Bulletin

Technical Service Bulletin: tsb101447	Released Date: 10-Jun-2004
Revision to Fault Code 482, Low Fuel Pressure	

Revision to Fault Code 482, Low Fuel Pressure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Fault Code 482 for the ISX Series engine.
--

Last Modified: 10-Jun-2004
