



Technical Service Bulletin

Technical Service Bulletin: tsb101531

Released Date: 01-Dec-2004

Revision of Water Pump Procedure

Revision of Water Pump Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service Parts Topic revises Procedure 008-062, Water Pump. This procedure affects for Signature, ISX and QSX15 engine series. The impeller cover removal and install steps are included.

Note : This is a product improvement, not subject to campaign.

Related Procedures

10-008-062

(/qs3/pubsys2/xml/en/procedures/10/10-008-062.html)

Water Pump

(/qs3/pubsys2/xml/en/procedures/10/10-008-062.html)

Last Modified: 01-Dec-2004