



Technical Service Bulletin

Technical Service Bulletin: tsb101591

Released Date: 05-Apr-2005

Crankshaft Inspection

Crankshaft Inspection

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces a new procedure for inspecting the ISX series engine crankshaft.

Related Procedures

10-001-016-topic
(/qs3/pubsys2/xml/en/procedures/10/10-001-016-topic.html)

Crankshaft
(/qs3/pubsys2/xml/en/procedures/10/10-001-016-topic.html)

Last Modified: 05-Apr-2005