



Technical Service Bulletin

Technical Service Bulletin: tsb101871

Released Date: 01-Jun-2006

Main Bearing Capscrew Torque Specification Change

Main Bearing Capscrew Torque Specification Change

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts topic supersedes 05T1-7. Please replace 05T1-7 with this topic.

This Service/Parts topic updates the torque procedure for ISX Main Bearing caps in Procedure 001-006.

The new torque value of 149 N•m [110 ft-lb] plus 180° has been validated for the MEX blocks (blocks after ESN 79012120) and will now be used on all engines.

The procedure change will affect **only** the torque specification. This eliminates the dual torque specifications on the ISX engine.

Note : This is a product improvement and is **not** subject to campaign.

Related Procedures

10-001-006
(/qs3/pubsys2/xml/en/procedures/10/10-001-006.html)

Bearings, Main
(/qs3/pubsys2/xml/en/procedures/10/10-001-006.html)

Last Modified: 01-Jun-2006