



Technical Service Bulletin

Technical Service Bulletin: tsb102031	Released Date: 28-Nov-2006
New Fault Code, 143, Engine Oil Pressure Low-Warning	

New Fault Code, 143, Engine Oil Pressure Low-Warning

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic announces the creation of a new fault code, 143, Engine Oil Pressure Low-Warning.
--

Engine Oil Pressure Low - Warning

Last Modified: 28-Nov-2006
