



Technical Service Bulletin

Technical Service Bulletin: tsb102099	Released Date: 18-Dec-2006
Revision, Guided Step 2D-2, Fault Code 222	

Revision, Guided Step 2D-2, Fault Code 222

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Step 2D-2 in Fault Code 222 in the Troubleshooting and Repair Manual, Electronic Control System, Signature, ISX and QSX15 Engines, Bulletin 3666259. The air pressure sensor, **not** the air temperature sensor, should be replaced in the event of a pin-to-pin short circuit in this check.

Ambient Air Pressure Sensor Circuit

Last Modified: 18-Dec-2006
