



Technical Service Bulletin

Technical Service Bulletin: tsb102172

Released Date: 08-Mar-2007

Revision, Install Step, (Bearing, Connecting Rod) Procedure

Revision, Install Step, (Bearing, Connecting Rod) Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds the connecting rod side clearance specifications to Procedure 001-005 (Bearing, Connecting Rod) in the Service Manual, Signature, ISX, and QSX15, Bulletin 3666239.

Related Procedures

10-001-005-tr
(/qs3/pubsys2/xml/en/procedures/10/10-001-005-tr.html)

Bearings, Connecting Rod
(/qs3/pubsys2/xml/en/procedures/10/10-001-005-tr.html)

Last Modified: 08-Mar-2007