



Technical Service Bulletin

Technical Service Bulletin: tsb102248	Released Date: 07-May-2007
New Fault Code 595, Turbocharger Speed High (Calculated)	

New Fault Code 595, Turbocharger Speed High (Calculated)

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds new Fault Code 595, Turbocharger Speed High (Calculated).

Turbocharger Speed High (Calculated)

Last Modified: 07-May-2007
