



Technical Service Bulletin

Technical Service Bulletin: tsb102275

Released Date: 25-Jul-2007

Revision, Install Step, Flywheel Procedure

Revision, Install Step, Flywheel Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 016-005, (Flywheel).

This update is to clarify the installation procedure for the ISX flywheel pilot bearing spacer.

Related Procedures

10-016-005-tr
(/qs3/pubsys2/xml/en/procedures/10/10-016-005-tr.html)

Flywheel
(/qs3/pubsys2/xml/en/procedures/10/10-016-005-tr.html)

Last Modified: 25-Jul-2007