



Technical Service Bulletin

Technical Service Bulletin: tsb102276

Released Date: 18-May-2007

Revision, Torque Value, Turbocharger Coolant Hoses Procedure

Revision, Torque Value, Turbocharger Coolant Hoses Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the torque value for the turbocharger coolant return hose banjo fitting in Procedure 010-041, Turbocharger Coolant Hoses.

Related Procedures

10-010-041-tr
(/qs3/pubsys2/xml/en/procedures/10/10-010-041-tr.html)

Turbocharger Coolant Hoses
(/qs3/pubsys2/xml/en/procedures/10/10-010-041-tr.html)

Last Modified: 18-May-2007