



Technical Service Bulletin

Technical Service Bulletin: tsb102373

Released Date: 06-Jul-2007

Revision, Leak Test Step, Cylinder Head Procedure

Revision, Leak Test Step, Cylinder Head Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 002-004 (Cylinder Head) to include the test kit, Part Number 3164943, used to test the fuel passages in the Leak Test step of the procedure.

Related Procedures

10-002-004-tr
(/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html)

Cylinder Head
(/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html)

Last Modified: 06-Jul-2007