



Technical Service Bulletin

Technical Service Bulletin: tsb102488	Released Date: 28-Sep-2007
Step Addition, Symptom Tree t047 (Engine Noise Excessive) and Symptom Tree t048 (Engine Noise Excessive - Combustion Knocks)	

Step Addition, Symptom Tree t047 (Engine Noise Excessive) and Symptom Tree t048 (Engine Noise Excessive - Combustion Knocks)

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds a step calling for the removal of the engine vibration damper, and for the engine to be operated in the RPM range where the noise or knock occurs, to symptom trees t047 and t048 in the Service Manual, Signature, ISX, and QSX15, Bulletin 3666239.

Engine Noise Excessive Engine Noise Excessive - Combustion Knocks

Last Modified: 28-Sep-2007
