



Technical Service Bulletin

Technical Service Bulletin: tsb102625

Released Date: 07-Jan-2008

Revision, Maintenance Schedule

Revision, Maintenance Schedule

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic removes Procedure 003-018 (Crankcase Breather Tube) from Section 8 (Maintenance Procedures at 200,000 Kilometers [125,000 Miles], 3000 Hours, or 2 Years) of the Signature and ISX Operation and Maintenance Manual, Bulletin 3666251. This procedure is already listed in Section 3 (Maintenance Procedures at Daily Interval). In addition, Procedure 102-002 (Maintenance Schedule) is revised accordingly in the Signature and ISX Operation and Maintenance Manual, Bulletin 3666251 and the ISX Engines Owners Manual, Bulletin 4960314.

Related Procedures

10-102-002-om-auto
(/qs3/pubsys2/xml/en/procedures/10/10-102-002-om-auto.html)

Maintenance Schedule
(/qs3/pubsys2/xml/en/procedures/10/10-102-002-om-auto.html)

Last Modified: 07-Jan-2008