



# Technical Service Bulletin

Technical Service Bulletin: tsb102632

Released Date: 04-Jan-2008

Revision, Multiple Steps, Camshaft Bushings Procedure

## Revision, Multiple Steps, Camshaft Bushings Procedure

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

This Service/Parts Topic revises Procedure 001-010 (Camshaft Bushings) in Section 1 to include camshaft bushing bore reuse specifications.

### Related Procedures

18-001-010  
(/qs3/pubsys2/xml/en/procedures/18/18-001-010.html)

Camshaft Bushings  
(/qs3/pubsys2/xml/en/procedures/18/18-001-010.html)

Last Modified: 04-Jan-2008