



Technical Service Bulletin

Technical Service Bulletin: tsb102696

Released Date: 03-Mar-2008

Revision, Multiple Steps, Turbocharger Wastegate Actuator Procedure

Revision, Multiple Steps, Turbocharger Wastegate Actuator Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic is revising Procedure 010-050 (Turbocharger Wastegate Actuator). The update is including the different adjustment procedures for the actuator end-link without a turnbuckle and actuator end-link with a turnbuckle.

Related Procedures

10-010-050
(/qs3/pubsys2/xml/en/procedures/10/10-010-050.html)

Turbocharger Wastegate Actuator
(/qs3/pubsys2/xml/en/procedures/10/10-010-050.html)

Last Modified: 03-Mar-2008